



The Ultimate Driving  
Machine



**INFORMATION.**  
**SOFTWARE UPDATE.**

# Contents

- Content ..... 2
- Conditions ..... 2
- Installation ..... 2
- Notes ..... 2
- Software update (TN & MN 002.045.001) ..... 3
- Software update (TN & MN 002.049.003) ..... 3
- Software update (TN & MN 002.052.001) ..... 3
- Software update (TN & MN 003.001.002) ..... 3
- Software update (TN & MN 003.003.001) ..... 3
- Software update (TN & MN 003.009.004) ..... 4
- Software update (TN & MN 003.011.002) ..... 4
- Software update (TN & MN 003.013.001) ..... 4

# Information about the software update

## Content

These instructions provide information about the software update.

The content of this software update depends on the software version of your vehicle.

For details about the software update and supported devices, please refer to the description below.

One of the following versions will be installed depending on your vehicle:

- ▶ HN 003.255.080 & MN 002.255.071 & TN 002.255.080
- ▶ HN 003.255.080 & MN 003.001.002 & TN 003.255.080
- ▶ HN 003.255.080 & MN 003.003.001 & TN 003.255.080
- ▶ HN 003.255.080 & MN 003.009.004 & TN 003.255.080
- ▶ HN 003.255.080 & MN 003.011.002 & TN 003.255.080
- ▶ HN 003.255.080 & MN 003.013.001 & TN 003.255.080

## Conditions

The software update is only available for certain vehicles that are equipped with the USB audio interface.

You can check if your vehicle is supported on the website under [www.bmw.com/update](http://www.bmw.com/update) or in the compatibility matrix under [www.bmw.com/bluetooth](http://www.bmw.com/bluetooth).

For more information about the software update, refer to the Owner's Handbook Navigation, Entertainment, Communication.

## Installation

The installation of the software updates requires the consent to the use rights conditions.

For this purpose, refer to [www.bmw.com/update](http://www.bmw.com/update).

For the installation, save the file for the software updates on a USB device to the main directory and connect the USB device at the centre arm-rest.

In addition, observe the notes in the Owner's Handbook Navigation, Entertainment, Communication under software update.

After installing the software update in the vehicle, the new software version will be displayed:

1. "My Vehicle"
2. "iDrive settings"
3. "Software update"
4. "Show current version"

## Notes

Switch off the vehicle at the end of the software update.

Transmitted data from external devices will be re-synchronized where required.

Tracks or playlists that were played back prior to the software update must be reselected.

This is also required for the restoration of earlier software versions:

1. "My Vehicle"
2. "iDrive settings"
3. "Software update"
4. "Restore software"

When the software is restored or updated by the service partner, manually generated changes for music files may be deleted.

If the following menu item is not displayed correctly after the software update, briefly deactivate Bluetooth for the installation:

1. "Communication"
2. "Manage mobile devices"
3. "Settings"
4. "Bluetooth:"

## Software update (TN & MN 002.045.001)

The software update makes the following adjustments:

### ConnectedDrive

- ▷ Improves ConnectedDrive Services.

### Notes

After installing the software update in the vehicle, the current software version will be displayed:

- ▷ HN 003.255.080 & MN 002.255.071 & TN 002.255.080

## Software update (TN & MN 002.049.003)

The software update makes the following adjustments:

### ConnectedDrive

- ▷ Improves ConnectedDrive Services.

### Notes

After installing the software update in the vehicle, the current software version will be displayed:

- ▷ HN 003.255.080 & MN 002.255.071 & TN 002.255.080

## Software update (TN & MN 002.052.001)

The software update makes the following adjustments:

### ConnectedDrive

- ▷ Improves ConnectedDrive Services.

### Notes

After installing the software update in the vehicle, the current software version will be displayed:

- ▷ HN 003.255.080 & MN 002.255.071 & TN 002.255.080

## Software update (TN & MN 003.001.002)

The software update makes the following adjustments:

### ConnectedDrive

- ▷ Improves ConnectedDrive Services.

### Notes

After installing the software update in the vehicle, the current software version will be displayed:

- ▷ HN 003.255.080 & MN 003.001.002 & TN 003.255.080

## Software update (TN & MN 003.003.001)

The software update makes the following adjustments:

### ConnectedDrive

- ▷ Improves ConnectedDrive Services.

## Notes

After installing the software update in the vehicle, the current software version will be displayed:

- ▷ HN 003.255.080 & MN 003.003.001 & TN 003.255.080

## Software update (TN & MN 003.009.004)

The software update makes the following adjustments:

### ConnectedDrive

- ▷ Improves ConnectedDrive Services.

## Notes

After installing the software update in the vehicle, the current software version will be displayed:

- ▷ HN 003.255.080 & MN 003.009.004 & TN 003.255.080

## Software update (TN & MN 003.011.002)

The software update makes the following adjustments:

### ConnectedDrive

- ▷ Improves ConnectedDrive Services.

## Notes

After installing the software update in the vehicle, the current software version will be displayed:

- ▷ HN 003.255.080 & MN 003.011.002 & TN 003.255.080

## Software update (TN & MN 003.013.001)

The software update makes the following adjustments:

### ConnectedDrive

- ▷ Improves ConnectedDrive Services.

## Notes

After installing the software update in the vehicle, the current software version will be displayed:

- ▷ HN 003.255.080 & MN 003.013.001 & TN 003.255.080